



# Carbide 3D

# Keyboard Shortcuts for Carbide Create and Motion

Carbide Create — deselects and returns to current pane

Carbide Motion — resets Grbl to factory defaults

Carbide Motion 4 — speed control  
1 = 0.01 mm 2 = 0.1 mm 3 = 1 mm 4 = Fast

Carbide Motion — Log window

Carbide Create (Mac OS X) — function backspace will delete the current selection

Carbide Motion — jog the Z-axis

Carbide Motion — speed control

Version 4  
1 = 0.01 mm  
2 = 0.1 mm  
3 = 1 mm  
4 = Fast

Version 3  
1 = Fast  
2 = Slow  
3 = 1 mm  
4 = 0.1 mm  
5 = 0.01 mm

Carbide Create — zoom in/out

Carbide Create — click-hold-drag on empty area to select

Carbide Create — click-hold-drag on empty area to pan

Carbide Create — click-hold dragging on a selection will move it with snapping (if enabled)

Carbide Create — click-hold dragging on a selection will move it without snapping

Carbide Motion — Arrow keys jog in the X/Y plane

Carbide Create — delete will delete the current selection

Carbide Motion — jog the Z-axis

Carbide Motion — MDI window

Carbide Create — control a will select everything

Carbide Create — control c will duplicate the current selection

Carbide Create — control-clicking on geometry will add or remove it from the current selection