



Carbide 3D

Keyboard Shortcuts for Carbide Create and Motion

Carbide Create — deselects and returns to current pane

Carbide Motion — resets Grbl to factory defaults

Carbide Motion 4 — speed control
1 = 0.01 mm 2 = 0.1 mm 3 = 1 mm 4 = Fast

Carbide Create — node edit toggle smooth/sharp

Carbide Motion — Log window

Carbide Create (Mac OS X) — function backspace will delete the current selection

Carbide Motion — jog the Z-axis

Carbide Motion — speed control

Version 4
1 = 0.01 mm
2 = 0.1 mm
3 = 1 mm
4 = Fast

Version 3
1 = Fast
2 = Slow
3 = 1 mm
4 = 0.1 mm
5 = 0.01 mm

Carbide Create — zoom in/out

Carbide Create — click-hold-drag on empty area to select

Carbide Create — click-hold-drag on empty area to pan

Carbide Create — click-hold dragging on a selection will move it with snapping (if enabled)

Carbide Create — click-hold dragging on a selection will move it without snapping

right-click (or control-click on toolpaths or group headings in the Toolpath pane for a menu which allows deletion.

Carbide Create — delete will delete the current selection

Carbide Create — shift- (414 and later) or control- (413 and earlier) clicking on geometry will add or remove it from the current selection

Carbide Create — control c duplicate the current selection

Carbide Create — control x delete the current selection

Carbide Create — control z Undo

Carbide Create — control a will select everything

Carbide Create — node edit delete selected nodes

Carbide Create — node edit toggle smooth/sharp

Carbide Create — control c duplicate the current selection

Carbide Create — control x delete the current selection

Carbide Create — control z Undo

Carbide Create — control a will select everything

Carbide Create — shift- (414 and later) or control- (413 and earlier) clicking on geometry will add or remove it from the current selection

Carbide Motion — jog the Z-axis

Carbide Motion — MDI window

Carbide Motion — Arrow keys jog in the X/Y plane
Create — nudge selection