



Info Top View Front View ISO View G-code 3D Test





Advanced VCarve Toolpath

Tool #1 (Pocket Tool)

#201 End Mill (1/4")

Edit...

Enable Area Pocket Tool

Cut Pockets First

Tool #2 (Vee Tool)

#302 Vee (60.0 degrees)


Edit...

Contours

1 Vector selected

Change Vectors

Select Current Vectors



Starting Depth (S) 0.000 in

Max Depth (D) 0.500 in

Inlay Plug Mode

Toolpath Name year

OK

Cancel