# Carbide 3D    Keyboard Shortcuts for Carbide Create

Carbide Create — (615 and later) Show Library (E)lements

Carbide Create — deselects and returns to current pane

Carbide Create —resets view
ctrl f resets view to stock only

Carbide Create — (521 and later) Layer window

Carbide Create (Mac OS X) — function backspace will delete the current selection

Carbide Create — control (command) z Redo

Esc  F1  F2  F3  F4  F5  F6  F7  F8  F9  F10  F11  F12

Prt Scrn Sys Rq    Scroll Lock    Pause Break

~ `   ! 1   @ 2   # 3   $ 4   % 5   ^ 6   & 7   * 8   ( 9   ) 0   _ -   + =   Backspace

Insert   Home   Page Up

Num Lock   /   *   −

Tab   Q   W   E   R   T   Y   U   I   O   P   { [   } ]   | \

Delete   End   Page Down

7 Home   8 ↑   9 Pg Up   +

Caps Lock   A   S   D   F   G   H   J   K   L   : ;   " '   Enter/Return

4 ←   5   6 →

Shift   Z   X   C   V   B   N   M   < ,   > .   ? /   Shift

1 End   2 ↓   3 Pg Dn   Enter

↑

Control   Super   Alt   Space   Alt   Super   Meta   Control

0 Insert   . Del

←   ↓   →

Carbide Create — control (command) c copy the current selection v paste

Carbide Create — control (command) d duplicate the current selection. Node edit delete selected nodes

Carbide Create — node edit toggle smooth/sharp

Carbide Create — control (command) x delete the current selection

Carbide Create — control (command) z Undo

Carbide Create — control (command) a will select everything

Carbide Create — shift- (414 and later) or control- (413 and earlier) clicking on geometry will add or remove it from the current selection

Carbide Create (473 or later) — enter/exit Node Edit mode

Create — nudge selection

Carbide Create — delete will delete the current selection

Carbide Create — click-hold-drag on empty area to select dragging up will select any object even partially in the selection area, down will only select objects entirely within the marquee

click-hold dragging on a selection will move it (with snapping if enabled)

Carbide Create — Zoom in/out in design/3D preview.

Carbide Create — click-hold-drag on empty area to pan

right-click (or control-click on toolpaths or group headings in the Toolpath pane for a menu which allows deletion, or on paths while node editing for options.