





Carbide Motion — speed control

- 4 Fast
- 3 1 mm
- 2 0.25mm
- 1 0.025mm



Carbide Motion — jog the Z-axis

Carbide Motion — Arrow keys jog in the X/Y plane